PART x ALLOY TABLE



Note: The table above is just an orientation. Is possible to use more then one alloy to have each part be done. The usage of the part must be observed before specifying the alloy.